

RESIDENTIAL SPLITS

Mingledorff's Technical Services / SE

03/19/2025


This presentation is intended for informational purposes only and does not replace legal advice or independent professional judgement.

Mingledorff's does not warrant the accuracy, completeness or usefulness of information available in this presentation.

Any reliance you place on such information is strictly at your own risk, and Mingledorff's will not be liable for any losses and damages in connection with your use of such information.

Attendees should note that sessions are audio-recorded and may be published in various media, including print, audio and video formats without further notice.

Dissipation Equipment




Dissipation Board Wiring

•Wiring diagram will be provided in installation instructions

• Fan coils will be factory wired

G, W and Y1 will be routed through the dissipation board R and C provide power to the board




DISSIPATION SYSTEM

Fan coils are prewired







DISSIPATION SYSTEM OPERATIONAL TESTS

Sensor Testing

- Power up with sensor connected wait for 10sec sensor warm up delay
- Ensure yellow status LED is on steady with no flashing (indicates sensor is communicating)
- Disconnect sensor from the dissipation board
- Verify that within 5sec the relays clicks, and the yellow status LED begins flashing fault code 2, this indicates the sensor is no longer communicating with the dissipation board

DISSIPATION SYSTEM

How it works

- In the event of a leak, the leak sensor sends a signal to the dissipation board, which energizes a blower to dissipate the refrigerant into the air stream.
 - Once activated, the blower is always on in dissipation mode and stays on for five minutes after the sensor readings are below the dissipation threshold.
- Dissipation board shuts down active heating or cooling call
- The system allows a heating or cooling call after 15 minutes of dissipation if the sensor is reading below the threshold.

- Each type of equipment will have a slightly different sequence of operation
 - Non-communicating residential splits
 - Communicating residential splits
 - Multi-family residential splits

Non communicating residential splits

- Once leak reaches 20% of the LFL the system will go into dissipation mode
 - Dissipation board LED will flash code 1 (dissipation in progress)
 - The Y1 and W relays will open
 - The G relay will close
 - After 15 min dissipation mode and the refrigerant detected is below 20% of the LFL compressor operation will resume as long as there is enough refrigerant to run the unit (low pressure switch)
 - If in heating mode, after 10 min in dissipation mode and the refrigerant detected is below 20% of the LFL, electric heat or gas heat will resume to satisfy the call
 - If the sensor still detects a refrigerant level that is 20% of the LFL 15 min, the board will determine that the sensor is faulty, heating and cooling will cycle but fan will remain on

Communicating residential splits

- Once leak reaches 20% of the LFL the system will go into dissipation mode
 - Dissipation board LED will flash code 1 (dissipation in progress)
 - Heating or cooling will stop
 - After 15 min dissipation mode and the refrigerant detected is below 20% of the LFL compressor operation will resume as long as there is enough refrigerant to run the unit (low pressure switch)
 - If in heating mode, after 5 min in dissipation mode and the refrigerant detected is below 20% of the LFL, electric heat or gas heat will resume to satisfy the call
 - If the sensor still detects a refrigerant level that is 20% of the LFL after 10 min, the board will determine that the sensor is faulty, heating and cooling will cycle but fan will remain on

•Multi-Family Splits (Midea)

- Once leak reaches 10% of the LFL the system will go into dissipation mode
 - Heating or cooling will stop
 - After 5 min dissipation mode and the refrigerant detected is below 10% of the LFL compressor operation will resume as long as there is enough refrigerant to run the unit (low pressure switch)
 - If in heating mode, after 5 min in dissipation mode and the refrigerant detected is below 10% of the LFL, electric heat will resume to satisfy the call
 - If the sensor still detects a refrigerant level that is 10% of the LFL after 10 min, the board will
 determine that the sensor is faulty, the unit will remain in dissipation mode with no heating or
 cooling allowed

•SPP

- SPP products will use the same sequence of operation as the non-communicating equipment
- Once leak reaches 20% of the LFL the system will go into dissipation mode
 - Dissipation board LED will flash code 1 (dissipation in progress)
 - The Y1 and W relays will open
 - The G relay will close
 - After 15 min dissipation mode and the refrigerant detected is below 20% of the LFL compressor operation will resume as long as there is enough refrigerant to run the unit (low pressure switch)
 - If in heating mode, after 10 min in dissipation mode and the refrigerant detected is below 20% of the LFL, electric heat or gas heat will resume to satisfy the call
 - If the sensor still detects a refrigerant level that is 20% of the LFL 15 min, the board will determine that the sensor is faulty, heating and cooling will cycle but fan will remain on

PURON ADVANCE™ FURNACE COILS

- 410A and Puron Advance[™] (454B) coils are not interchangeable.
- If an outdoor Puron Advance[™] unit is used to replace an existing 410A unit, the indoor coil must be replaced with a Puron Advance[™] coil
- All Puron Advance[™] models ship with a dissipation sensor factory installed with the cable and harness attached.
 - A separate box with a dissipation board, enclosure and wiring harness will be shipped inside the coil packaging to connect to the furnace
- Puron Advance[™] furnace coils will be compatible with Puron Advance[™] AC/HP units
 - Always check MyCarrierRatings to determine system combinations

A COIL MULTIPOISE SENSOR LOCATION

Grommet modification and straight stub-outs





Sensor location



SLAB COIL SENSOR LOCATION

Grommet modification and straight stub-outs





Sensor location




THERE'S A NEW SENSOR IN TOWN








DISSIPATION BOARD WIRING – INFINITY/EVOLUTION



- Dissipation Board is Communicating for Deluxe Models
 - ABCD connection header will be used
 - •(A, B and C wires)
 - •8-pin connector also partially used
 - •(R,C, (& G on furnaces)
 - Function remains the same



NOTE: Dissipation terminal is only used on Carrier communicating furnaces manufactured Q4 2023 and later. Use a 3/16" spade connector on the GRN/VIO wire to connect to the dissipation terminal on communicating furnaces. Attach wire nut to all unused wires from the power harness.


Fig. 21 – Wiring Layout, Communication Unit

A230462

Mingledorffs

Table 3 - Communication Plug Designations

CCN Plug Connections					
Color	GRN	YEL	WHT	RED	
Signal	Α	В	С	D	




NEW OUTDOOR LABELS-OUTSIDE CONTROL PANEL COVER

	A				_	
	A WARNING			ADVERTENCI	A	
	ELECTRICAL SHOCK HAZARD WARNING: RISK OF ELECTRIC SHOCK. CAN CAUSE INJURY OR DEATH: DISCONNECT ALL REMOTE ELECTRIC POWER SUPPLIES BEFORE SERVICING.					
4	RISQUE D'ÉLECTROCUTION ATTENTION: RISQUE DE DÉCHARGE ÉLECTRIQUE POUVANT CAUSER DES BLESSURES OU LA MORT. DÉCONNECTER TOUTES LES ALIMENTATIONS ÉLECTRIQUES AVANT L'ENTRETIEN.					
	RIESGO DE DESCARGA ELÉCTRICA					
	ATENCIÓN: RIESGO DE DESCARCA ELÉCTRICA, PUEDE CAUSAR LESIONES O LA MUERTE: DESCONECTE TODAS LAS ALIMENTACIONES ELÉCTRICAS ANTES DE DAR MANTENIMIENTO.					
Jer	EXPLOSION HAZARD System under pressure. Relieve all pressure and recover refrigerant before system repairs or final disposal. Use all service ports.					
*	RISQUE D'EXPLOSION Système sous pression. Relever toutes pressions et recouvrir le réfrigérant avant d'entreprendre les travaux d'entretien ou disposition finale da produit. Utiliser tous les ports de service.					
		RIESGO DE EX				
	Sistema bajo presión. Libere toda la presión y Utilice todos los puertos de servicio.	recupere el refrigerante antes de repar	rar el sistema o de la dispo	sición final del producto.		
			Refrigeran	t		
	<	V	Safety Grou	IP		
		\leq	Á2L			
	NINC: Rick Of Eiro	Elammable Pofri	gerant Lleed	To Be Repaired	Only	
WARNING: Risk Of Fire. Flammable Refrigerant Used. To Be Repaired Only By Trained Service Personnel. Do Not Puncture Refrigerant Tubing.						
AVERTISSEMENT – risque d'incendie. Frigorigène inflammable utilisé. Doit uniquement être réparé par du personnel d'entretien formé. Ne pas percer les conduites de frigorigène.						
ADVERTENCIA: Riesgo de incendio. Utiliza refrigerante inflamable. Solo personal de servicio capacitado debe reparar el dispositivo. No perfore la tuberia de refrigerante						
WARNING: Risk Of Fire. Dispose Of Properly in Accordance With Federal Or Local Regulations. Flammable Refrigerant Used.						
AVERT Frigorig	SSEMENT – risque d'incendie. Élin gène inflammable utilisé.	niner correctement conformé	ment aux réglements	ations fédérales ou locales.		
ADVER Utiliza i	TENCIA: Riesgo de incendio. Desc refrigerante inflamable	artar la unidad de forma adec	uada según las regu	laciones federales o locales.		
WARNING: Risk Of Fire. Flammable Refrigerant Used. Consult Repair Manual/Owner's Guide Before Attempting to Service This Product. All Safety Precautions Must be Followed.						
AVERTISSEMENT – risque d'incendie. Frigorigène inflammable utilisé. Consultez le manuel de réparation/guide du propriétaire avant de tenter d'effectuer l'entretien de ce produit. Toutes les consignes de sécurité doivent être respectées						
ADVERTENCIA: Riesgo de incendio. Utiliza refrigerante inflamable. Consulte el Manual de reparación/Guia del propietario antes de intentar realizar el mantenimiento de este producto. Se deben seguir todas las precauciones de seguridad						
FIRE HAZARD Do not use torch to remove components. Oil may catch fire. Use tabling cutter. Use caution when servicing compressor. Damaged or weakened fusit@pins could allow oil and mitigrarant to vent under pressure.						
RISQUE DE FEU Ne pas utiliser une torche pour retirer les. Huile peut prendre feu. Utiliser une coupe-tube. Soyez prudent lors de l'entretien du compresseur. Au cas où les epaingles du fusible de la fiche maie sont endommagées ou affabilites, ils pouraient permenttre à h'uile et au aritrigérant de s'échapper sous pression.						
RIESGO DE INCENDIO No utilice sopiete para remover componentes. El acelte puede incondiarse. Use un contador de tubos. Tenga cuidado al dar servicio al compresor. Los pasadores fusite dariados o debilitados podrían permitir que al aceltar y el refrigierante se ventilan bajó presión.						
		SERVICE/SERVICE/S	SERVICIO			
~		USE ONLY R-454B REFRIGERANT AND APPR Refer to product literature before inst	OVED SYNTHETIC COMPRESSO tailing or Servicing this unit.		88 ·	
	Added Charge	Carga inicial Carga adicional		ge initiale ge ajoutée 3497	97-101 REV.C	

	SERVICE/SERVICE/SERV			
USE ONLY R-454B REFRIGERANT AND APPROVED SYNTHETIC COMPRESSOR OIL Refer to product literature before Installing or Servicing this unit.				
Initial Charge	Carga inicial	Charge initiale	13764	
Added Charge	Carga adicional	Charge ajoutée		
 			349797-101 REV.C	

Mingledorff

NEW OUTDOOR LABELS-INSIDE CONTROL PANEL COVER



Total System Charge (Ibs.)	Minimum Floor Area (sq.ft.)	
4	61	
4 5 6 7	76	
6	91	
7	106	
8	122	
9	137	
10	152	
11	167	
11 12 13 14	182	
13	198	
14	213	
15 16	228 243	
	243	
17	258	
18	258 274	
19	289	
20	304	
21	319	
21 22 23	335	
23	350	
24	365	
25	380	

Mingledorffs

Total Refrigerant Charge (Ibs)

Initial + Added _____ =Total

Reported Situation	Status	Implementation Date (Week/Year)
Liquid/Suction tube door grommets - loose	Complete	0224J

Condition reported:

Liquid and suction stub grommets were not staying in panel opening around tube. Created air leaks and a poor-quality perception. **Solution:**

Grommets were resized to fit into panel opening while creating a tight seal on copper stubs.





Reported Situation	Status	Implementation Date (Week/Year)
Liquid/Suction tube plugs - leak	Complete	0624J

Condition reported:

Nitrogen is leaking out of coils around rubber plugs. Customer perspective –if they don't hear gas escaping from coil when removing plugs, the coil has a leak.

Solution:

Nitrogen pressure was adjusted, and rubber plug material was changed to maintain a higher pressure in coils, so customers could hear gas escape during plug removal.



Mingledorffs

OUTDOOR SPLIT SERVICE VALVES

Situation: We continue to receive reports that the service tech are unable to open the service valves. The hex socket inside of the valve has become "stripped" and can't be opened.

Findings: Upon investigation of the reports, we are finding the hex socket isn't completely "stripped" the entire length of the socket. When a valve is tight the multi-step tool being used by the service tech isn't engaging enough of the socket & stripping the valve.

- Liquid Service Valve Full Insertion Depth is 1-3/8"
- Suction Service Valve Full Insertion Depth is 1"

Recommendation: Don't use the hex multi-size tool because is doesn't all full engagement to the bottom of the valve socket. Especially when breaking the valve free for the first time. Use the standard hex "Allen" wrenches that fit the entire socket depth or purchase the correct depth hex multi-size tool.







COPELAND K7 COMPRESSOR INVESTIGATION

- Reverse rotation may produce a short duration sound at shutdown; lasting until discharge and suction gas pressure equalizes.
- While reverse rotation noise does not damage the compressor and has no impact on compressor reliability, the noise may be objectionable to some customers.
- A design change internal to the compressor has been implemented on Copeland 3.5, 4, and 5ton K7 compressors manufactured after December 1, 2024, that eliminates most reverse rotation noise at shutdown.



Mingledo

PRESSURE SWITCH UPDATE – GAS FURNACE

 We have received increased reports of stuck closed pressure switches in our furnaces.

ngled

- Switch Part # HK06MB012, HK06MB020, and HK06MB021
- On Max deflection of the switch diaphragm (> 2.0" negative pressure), friction between the diaphragm and housing may cause the diaphragm to lightly bind to the housing edge when the vacuum drops after firing of the unit.
- This could be a temporary condition and may release spontaneously or by a light tap on the switch.
- All inventory at Replacement Components has been purged of any suspect switch.

80% KINKED PRESSURE SWITCH CROSSOVER HOSE

ISSUE STATEMENT

Reports of pinched crossover tube on non-condensing furnace two-stage pressure switch assemblies

2 CONTRIBUTING FACTORS

Original Honeywell equipped switch set had different pressure port angle and spacing. When switch was transitioned to MTI, the hose material was not changed.

CORRECTIVE ACTION

3

Tube to be changed to square style tubing like the pressure hose used on current condensing furnaces connecting the inducer housing to the Housing Pressure Switch ST FORMULA

Mingledorffs

Implementation: Week 23, 2024

OUTDOOR SPLITS MISSING SERVICE CAPS

Report:

Multiple reports about missing service valve caps both liquid line and suction line of condenser units, most of the units were built at CMX-C during 2024.

Problem Description

What? Missing caps on service values.
Why? Values have no protection.
Who? Field Reports
When? June 17, 2024.
Where? Northeast / Midwest
How much? multiple serial number reports

Solution:

Added witness marks on each service valve. Placed more service valve caps at end of run test. Issued a Factory Quality Alert to all lines. Reports



perador Service Valve: asegurar poner los tapones de bronce en ambas válvulas haciendo el roscado completo manualmente, y asegurar poner los tapones de hule en la tuberia sin rosca.

Mingledorffs




Witness mark applicable since Wk 26, 2024



V COIL SENSOR LOCATION

Grommet modification and straight stub-outs





Sensor location

